#### Annex I, Part B

#### **Appendix VII: EXPECTED DURATION OF INDIVIDUAL TASK**

#### EDITORIAL NOTE

This report has been prepared from the original material as submitted for publication and has not been edited by the editorial staff of the IAEA. The views expressed do not necessarily reflect those of the IAEA or the governments of its Member States.

It does not address questions of responsibility, legal or otherwise, for acts or omissions on the part of any person.

The use of particular designations of countries or territories does not imply any judgement by the publisher, the IAEA, as to the legal status of such countries or territories, of their authorities and institutions or of the delimitation of their boundaries.

The mention of names of specific companies or products (whether or not indicated as registered) does not imply any intention to infringe proprietary rights, nor should it be construed as an endorsement or recommendation on the part of the IAEA.

The depiction and use of boundaries, geographical names and related data shown on maps do not necessarily imply official endorsement or acceptance by the IAEA.

The IAEA has no responsibility for the persistence or accuracy of URLs for external or third party Internet web sites referred to in this report and does not guarantee that any content on such web sites is, or will remain, accurate or appropriate.

Line no.	Subtask	Photo alimin	Referent draming of the companies of the	Strategy 2	S. S	To be Prochamen by	Accessary to the said	Personal projection of the state of the stat	Some Marie Some South of the So	4 switch to the factor of the	Special dismeering to the line of the line	Waste Committee of the Control of th	t o sinding	E. Decrete de la constante de	Proceeding we have been a second to the seco	C. Doctor Jadiship	Elpered among of	E. Decreed amounts of lands of
1	Work going on during	the whole opera	ntion															
2	Taking photos/videos					KL	Cameras with fully charged batteries	Safety helmet where required						?	?			
3	Marking of the dismantled parts		Memo on identification and marking of graphite blocks		Radiation from the graphite Drop of graphite stringer	PEB	Tape, speedmarker	Gloves (graphite)			Possibly finger dosimeters							
4	Documentation of the work and the dismantled parts		Task description Waste ID guide			KL/PEB	Necessary forms. Possibly a PC											
5	Preparatory work:																	
6	1" Al-pipe going through the core vessel (the glory hole pipe) cut loose and taken out					НЈ/РЕВ												
7	Order 2 concrete shielded drums for the core vessel, drain pipe and connecting pipe					НЈ/РЕВ												
8	Provide containers for other waste and decide where to place these			"Blue" pallet containers and containers for small active samples (plastic bottles and a lead bucket)		НЈ/РЕВ												
9	Produce lifting gear for the core vessel	Photo 5215 and 5216	71203	Must be certified		НЈ												
	Mount rails and skirting board on top of the biological shield					НЈ/НҮ												
11	Mount the swinging crane			Must be able to reach all the way over the reflector tank and over the roof of the control rod house		НЈ/НҮ		Safety helmet										
12	Prepare the suction pads			Ascertain that the supply of pressurised air is OK		НЈ/НҮ												
13	Test the function of the swinging crane and the suction pads			Simulate removal of a stringer from the reflector tank and transfer to a pallet container placed at the roof of the control rod house	Risk of falling down on the reflector tank	HJ/HY, PEB KL, RPT	,	Safety line		Х				?				
14	Produce a frame to center the core vessel in the waste drum					НЈ												
15	Prepare shielding of the core vessel and connecting pipe during the removal of the first 7 layers of graphite					PEB, HJ, BL												

Line no.	Subtask	Phon Guinn	Recernit draming or	Annuar k	39	Pake perfined by	Necessary looks and	Personal Projection addition to Section 10 S	Other Discontinus	Assistance by Coching Deco.	Special dosineers to	Naste Comainer to be	Samples to be taken to be to be taken to be to b	Proceed in the Control of Control	Expected amounts of Innivitie of
16	Plan measurements of radiation levels and health physics surveillance					AHF, KL									
17	Initial work:	,													
18	experimental channels	Photos from the characterisation report		Intermediate storage in the reactor hall		SBJ m.fl.	Pallet and pallet transporter								
19	Removal of concrete shielding blocks at the top of the reactor	Photos from the characterisation report		Intermediate storage in the reactor hall											
20	Remove the steel tray on top of the reflector tank	characterisation report		Intermediate storage in the reactor hall											
21	Inject plastic foam into the connecting pipe between the core vessel and the recombiner	Photo no. 5215	971201	Blind plate to be replaced afterwards	Incomplete filling of the pipe	НЈ/НҮ	Plastic "stocking" to pull the pipe into				Finger- and wrist dosimeters		?		
22	Remove the shielding blocks between the reflector tank and the lead wall to the recombiner vault	Photo IMG_1257		The blocks may be slightly activated	Dropping blocks	НЈ/НҮ	Lifting gear				Finger- and wrist dosimeters	"Blue" pallet container			
	Measure radiation levels Establish the working place				Slippery floor at	RPT			Lay on non-						
24					the top	HJ/HY			skid coating of the floor						
25	Cutting of the connecting pipe in the space between the reflector tank and the concrete shield	Photo IMG_1257		Possibly apply a lead plate to shield the pipe	Contamination from escaping material	НЈ/НҮ	Saw and a tray or similar for collecting chips	Safety helmet, dust mask	Prepare exhaustion		Finger- and wrist dosimeters		Chips to be collected now. Slices of the pipe to be cut out later		
26	Removal of the lead wall between reactor vault and recombiner vault	Photos IMG_1226 og IMG_1257		Intermediate storage in the reactor hall - remember plastic cover of the floor	Drop of lead wall during transport	НЈ/НҮ		Safety helmet						30 minutes	
27	Removal of the free end of the connecting pipe, including the flange, and transfer to the waste drum				Contamination from escaping material	НЈ/НҮ	Lid or plastic bag to cover the open ends of the pipe		Prepare exhaustion		Finger- and wrist dosimeters	Concrete- shielded drum (possibly plastic bag and placement in shielded cell)			0
28	Checking the radiation levels in the recombiner vault			Low radiation level expected		RPT				X					
29	Removal of isolated cooling pipes in the recombiner vault					НЈ/НҮ		Safety helmet		X					
30	Fuel level indicator to be cut free from the drain pipe					HJ/HY	Tray or similar for collection of possible fluid	Safety helmet							
31	The drainpipe to be cut and checked for possible content of fluid					НЈ/НҮ	Container for collection of fluid	Safety helmet							

Line no.	Subtask	Hanification in	Rechail champs or champs or	Ponum K.	39	Po be performen by	Accessor tools and	Safety belief	Safety Sa	Assistance by the continue by	Special distribution of the breed distributi	New Commence to be	Sommers to p.	Chorden Charles Alexandra Char	Ti hour	Checker animin	Especial annual control of the contr	Epechel ammin of linits of linits of
32	Removal of pipes and valves in the recombiner vault				Risk of injury to head Risk of escape of core fluid	НЈ/НҮ	Container for collection of fluid. Box spanners, wrenches, screwdrivers, hacksaw	Safety helmet	Exhaustion prepared Air monitor active	х		Strong plastic.	Pipes to be cut close to where they enter into	35-130 μSv/h	1 hour	50 μSv	10 kg	10 kg
33	Tidying and cleaning in the recombiner vault					HJ/HY												
34																		
35	Drilling out the drain p				Risk of injury to		Hole-saw	Safaty halmat				Diagtic has	The cut out	35-100 μSv/h	10 minutes	10 μSv		
36	the drain pipe where it protrudes from the reflector tank				head. Heating of the graphite inside the tank	НЈ/НҮ	Hole-saw	Safety helmet		X			piece is in itself a sample	33-100 μ <b>3</b> V/fl	To minutes	10 μον		
37	Weld a mounting for the drilling machine on the reflector tank and mount the drilling machine				Risk of injury to head Heating of the graphite inside the tank	НЈ/НҮ	Welding equipment	Safety helmet		х				35-100 μSv/h	20 minutes	20 μSv		
38	Drill a core of reflector graphite with the drain pipe in the centre until the drain pipe is cut below the core vessel			Graphite powder will be produced during drilling	Risk of injury to head Heating of the graphite inside the tank	НЈ/НҮ	Core-drill Vacuum cleaner Plastic for wrapping up drilled-out material	Safety helmet, dust mask		X		Plastic bags The drain pipe to be placed in the shielded cell		35-100 μSv/h	1 hour	35 μSv	500 g	2 kg (graphite)
39	Removal of graphite a	nd core vessel																
40	Graphite stringers in layers no.13 to no. 9 to be removed, weighed, marked, registered and transferred to pallet containers		71101 - 1 & 2	Remember shielding of the core vessel and the connecting pipe (e.g. using bags with lead bullets in the central hole)	reflector tank Drop of graphite blocks	Removal: HJ/HY Marking: PEB	(pressurized air), guide rod, swinging crane, "HF-tape", speed	masks	Exhaustion prepared Air monitor active	X			Selected stringers to be put aside in accordance with instructions from waste characterisa- tion lab.	1-50 μSv/h	7 hours	80 μSv		
41	Cutting of the connecting pipe in a plane less than 16 cm from the centre of the core vessel	Photo no. 5215	971201, 71203, 71205		from escaping material	НЈ/НҮ	or similar for collecting chips	Dust mask	Exhaustion prepared Air monitor active	X	Finger- and wrist dosimeters		Later	300-800 μSv/h	10 minutes	80 μSv		
42	Transfer of the cut-off pipe to a concrete shielded drum				Pipe stuck in tank wall	НЈ/НҮ	Long-handled tongs Plugs for the pipe-ends	Dust mask	Exhaustion prepared Air monitor active		Finger- and wrist dosimeters	Concrete- shielded drum		50-300 μSv/h	5 minutes	10 μSv		
43	Cutting out samples from the wires to thermo elements	Photo no. 5215				НЈ/НҮ	Long-handled tongs and gripping tool			X	Finger- and wrist dosimeters	Sample container		50 μSv/h	1 minute	1 μSv	0,5 kg	
44	Cutting loose the wires to the thermo elements	Photo no. 5215		Remember shielding of the core vessel and the connecting pipe		НЈ	Long-handled nippers				Finger- and wrist dosimeters			300-2000 μSv/h	1 minute	5 μSv		

Line no.	Subtask	Photo min in	A Constant of the Constant of	S. Human M. S.		To be performen by	Other State of the	Possibly dust	Super Distriction of the Control of	Assistance by Gerralian Co.	Special and an	Waste committee of the	A CO SOUTH	Social So	To minutes to the first to the	The control of the co
45	Mounting a lifting collar on the pipe end at the top of the core vessel	Photo no. 5215	71203	Remember shielding of the core vessel and the connecting pipe (e.g. using bags with lead bullets in the central hole)	Fall into the hole		Lifting collar and appropriate tools	1 Ossibiy dust	Exhaustion prepared Air monitor active		Finger- and wrist dosimeters			300-2000 μSv/h	2 minutes	10 μSv
46	The necessary number of graphite stringers from layers 8 and 7 to be removed, weighed, marked, registered and trasferred to a pallet container	Photo no. 5215	71101 - 1 & 2	Remember shielding of the core vessel and the connecting pipe	Drop of graphite stringers	Removal: HJ/HY Marking: PEB	(pressurized air), guide rod, swinging crane, "HF-tape", speed	Possibly dust masks	Exhaustion prepared Air monitor active	X		Pallet container	Selected stringers to be put aside in accordance with instructions from waste characterisa- tion lab.	60 μSv/h	2 hours	90 μSv
47	Ensure that the core vessel is free and can be lifted					НЈ			Exhaustion prepared Air monitor active		Finger- and wrist dosimeters				2 minutes	
48	Check the maximum cross section of the core vessel in order to ensure that it can go into a shielded drum			No problem if no pipes protrude beyond the diameter of the vessel		НЈ					Finger- and wrist dosimeters			800 μSv/h	2 minutes	25 μSv
49	Weigh the core vessel			May be done during the actual lifting out of the vessel		HJ/HY/KL	Weighing cell	Dust mask	Exhaustion prepared Air monitor active	X	Finger- and wrist dosimeters			120 μSv/h	2 minutes	5 μSν
50	Lifting out the core vessel and transferring it to a shielded drum and mounting the lid on the drum				Contamination from escaping material	НЈ/НҮ	Approved lifting gear	Dust mask	Exhaustion prepared Air monitor active		Finger- and wrist dosimeters	Concrete shielded drum		120 μSv/h 800 μSv/h	5 minutes 1 minut	10 μSv 30 kg 10 μSv
51	Place the drum in a shielded cell in the reactor hall				Dropping of the drum from the crane		Approved lifting gear				Finger- and wrist dosimeters			60 μSv/h	5 minutes	5 μSν
52	If necessary fill the drum with steel balls and/or low- active metal parts for extra shielding					НЈ/НҮ					Finger- and wrist dosimeters				10 minutes	
53	Remove the remaining graphite stringers			considered to send a man down into the	Drop of graphite stringers Contamination on the stringers	Removal:	(pressurized air), guide rod, swinging crane, "HF-tape", speed	masks	Exhaustion prepared Air monitor active	X		Pallet container	Selected stringers to be put aside in accordance with instructions from waste characterisa- tion lab.		4 hours	
54	Check the radiation level inside and on the outer surface of the reflector tank				Fall into the hole	RPT				X					5 minutes	

Line no.	Subtask	Henification in	Cheran chaming or cham	\$ June	Signal Control of the	To be performed by	Mecsing to the said	Safety belmet	S SHEY.	Assistance by the control of the con	Special merina De cita dosineers to	Waste Committee of the Party of	Samples to be called the property of the prope	4 hours	Especiel amounts of limit, ive
55	Remove experimental channels between reflector tank and concrete walls	Photo no. IMG_1250, IMG_1253, IMG_1254 og IMG_1257	betv and tigh tape othe char to tl	ween the channels the tank are only tend by means of e, while in the er end the nnels are welded he steel plates on biological shield	The channels may be (slightly) activated close to		or similar for	Safety helmet, possibly dust masks		X - depending on radiation level		"Blue" pallet container		4 hours	
56	Loosen and lift out the reflector tank	Photo no. 5218 A, 5218 B, IMG_1251 og IMG_1252	the plac Ten the If n shie	e tank is bolted to floor in four ces. inporary storage in reactor hall. ecessary, elding must be ablished.		HJ/HY + possibly more	Approved lifting gear	Safety helmet	Floor to be covered by plastic where the tank is to be placed	X - depending on radiation level				1 hour	
57	Final work:														
58	Carry out measurements for sorting of waste (into active and potentially non-active) and take samples of waste to be disposed of as radioactive		to b	tructions for this be given by the ste Treatment int		HJ/HY RPT						Possibly container for samples			
59	Check radiation levels around the shielded cell					RPT									
60	Check radiation levels in the reactor vault					RPT									
61	Tidying and cleaning in the reactor vault					HJ/HY				evt.					
62	Finalise the accounting of personnel doses					RPT/HF/KL									
63	Input data to data base Write the report about the work					HF/KL KL									

#### Acceptance of the plan

Role/Unit	Name	Acceptance date
Project leader	PL	sign. 12.01.2005
Workshop	Responsible WS	sign. 12.01.2005
Health physicist	Responsible HF	sign. 15.01.2005
Waste treatment plant	Responsible WTP	sign. 16.01.2005
Safety group	Responsible SG	sign 16.01.2005

**Date for revision:** 12 January 2005

#### Acronyms used:

AHF	Applied Health Physics	KL	Projekt Leader
AS	Worker A. S.	PEB	Worker P.E.B
BL	Worker B. L.	RPT	Radiation protection technician
HF	Health physicist	SBJ	Worker S.B.J
НЈ	Worker H. J	SC	Worker S.C.
НҮ	Worker H. Y.		