





Énergie NB Power

Life Extension of the Point Lepreau GS – Powering the Future

**Keith Stratton
New Brunswick - Canada**

October 27 – 30, 2009


International Conference on Opportunities
and Challenges for Water Cooled Reactors
in the 21st Century



Outline

- Company profile
- Station design
- Early performance
- Operational challenges
- Refurbishment review
- Summary


NB Power Group



- 86-year-old government-owned utility
- Holding company and four operating companies

NB Power Overview

- Nuclear, Oil, Coal, Gas, Petcoke, Hydro, Diesel, Wind
- 20,284 kilometres of distribution line
- North America's most diverse networks of generating stations with installed net capacity of 3,959 MW
- Interconnects with Quebec, Maine, Nova Scotia and Prince Edward Island
 - export capacity 2,416 MW
 - Import capacity 2,209 MW



Point Lepreau G.S.

Point Lepreau Generating Station

- ~750 employees
- First criticality: July 1982
- Commissioned in 1983 - 100% full power in March 1983
- Supplies approximately 25% -30% of in-province load
- Eliminates the need for 162 million barrels of oil
- Averted emissions of about 87 million tonnes of CO₂ during its first lifetime
- Produced 114 million MWh of power
- Lifetime capacity factor of 82%

635 MW net CANDU 6 reactor




NB Power – Safety our Top Priority


- NB Power became the first full service utility in Canada to reach 12 consecutive months without a lost time accident
- Point Lepreau Generating Station
 - Point Lepreau G.S. staff achieved more than 4.8 million person-hours without a lost-time accident
 - AECL staff and contractors achieved more than 3.5 million person-hours without a lost-time accident
 - Integrated joint health and safety committee with all on-site contractors and NB Power
 - Continue to maintain some of the highest standards for health, safety and training throughout refurbishment and beyond



Reactor Assembly




Basic schematic



- LIGHT WATER STEAM
- LIGHT WATER CONDENSATE
- HEAVY WATER PHIT
- HEAVY WATER MODERATOR
- SALT SEA WATER

Heat transport system



Inlets

- 265 Celsius
- 11 Mpa
- 1.5 - 2.5" NPS

Outlets

- 310 Celsius
- 10 MPa
- 2 - 2.5" NPS

Early operation – to 1994

- Annual outages < 30 days
- Average capacity factor = 93.4%
- Very low operating costs
- Established inspection programs
 - fuel channels
 - steam generators
 - turbine/generator

Onset of ageing issues – mid-'90s


- Fuel channels
- Feeders
- Safety system trip logic
- Station control computers
- Uninterruptable power supply
- Turbine supervisory

Consequence: average capacity factor over the last half of the station's life = 72%

Nuclear safety culture remained strong

Safety margins were maintained

Fuel Channel Assembly




Fuel channels

- Spacer movement
 - Loose fitting spacers may move from design locations
 - Would not operate with contact between cool calandria tube and hot pressure tube – hydride solubility
 - One six-month outage (1995) and subsequent outage extensions
- Pressure tube (PT) diametral creep
 - Redistribution of coolant flow in bundle sub-channels with time
 - Reduction in margin to sheath dryout
 - Reactor derated 1998, ~1% per year (12% cumulative by 2008)

Feeders

· Cracking (outlets)

- Unplanned outages in 1997 and 2001 because of leaks at bends
- Large annual inspection campaign initiated
- Cracks discovered on the ID on bend intrados
- Cracks discovered on the OD on bend extrados
- Cracks grew from undetectable to 75% through wall in one year
- Crack location unpredictable
- Stress corrosion cracking and low temperature creep cracking
- Eighteen bends replaced because of cracking
 - › two through wall
 - › ten partial through wall
 - › six falsely identified



Feeders (continued)



Feeders (continued)



Feeders (continued)



▪ Thinning (outlets)

- Excessive thinning at bends on outlet feeders in 1995
- Large annual inspection campaign initiated
- Predictable rate and location
- Flow Accelerated Corrosion
- Affected bends in six feeders replaced in 2005

Life extension process

- 1997/1998
 - Concluded refurbishment of the station was an economical option to other sources of energy
- 1999 - 2002
 - Condition assessments of the systems
- 2005
 - Refurbishment decision
- 2008 March
 - Refurbishment outage started

Refurbishment Outage Scope Drivers

- Safety
 - improved trip coverage
 - improved Core Damage Frequency
 - improved Large Release Frequency
 - codes and standards compliance
 - miscellaneous regulatory issues
- Economics (necessary and sufficient)
 - near end of life
 - reliability improvement
 - obsolescence
 - alternate operating cycle post-refurbishment

} Level 2 PSA

Scope Determination

- Safety improvements
 - SDS1 and SDS2 trip coverage
 - Add containment filter vent
 - Add emergency source of water to calandria vault
 - Enhance moderator sub-cooling capability
 - Install Hydrogen recombiners
 - Install 3rd Standby Diesel Generator
 - Install 4th Recirculating Cooling Water pump
 - Upgrade fire protection throughout the power block
 - Install ventilation system for MCR

Scope Determination (continued)

- Age management/improve equipment condition
 - Replace fuel channels
 - Replace feeders } Retube
 - Calandria internal inspection
 - Rewind generator
 - Replace Shutdown System trip computers
 - Replace UPS
 - Replace vanadium flux detectors
 - Clean primary side of boilers
 - Inspect primary and secondary side of boilers
- Turbine uprate

Phases of Refurbishment

- Stage 1 - Defuelling and draining
 - Completed on schedule in 2 months
- Stage 2 - Executing the outage work
 - In progress
- Stage 3 - Commissioning and return to service
 - Commissioning started where possible

Specialized Tooling



Pressure Tube Volume Reduction




Checker board shear press



Processed tube segments

Complex Job - Pressure Tube Removal




Refurbishment Outage Scope - status

- Safety improvements
 - SDS1 and SDS2 trip coverage
 - Add containment filter vent
 - Add emergency source of water to calandria vault
 - Enhance moderator sub-cooling capability
 - Install Hydrogen recombiners
 - Install 3rd Standby Diesel Generator
 - Install 4th RCW pump
 - Upgrade fire protection throughout the power block
 - Install ventilation system for MCR

Status (continued)


- Age management/improve equipment condition
 - Replace fuel channels
 - Replace feeders } Retube
 - Calandria internal inspection
 - Rewind generator
 - Replace Shutdown System trip computers
 - Replace UPS
 - Replace vanadium flux detectors
 - Clean primary side of boilers
 - Inspect primary and secondary side of boilers
-
- Turbine uprate

Retube status



- Disassembly complete
 - End fittings removed
 - Pressure tubes removed
 - Calandria tubes removed
 - Feeders removed
- Inspections in progress
- Installation of upper feeders begun


Calandria Vessel Inspections



Replacement of 780 Feeders



Retube next steps



- Upper Feeder Installation in parallel
- Complete inspections
- Calandria Tube installation
- Install Pressure Tubes
- Install End-Fittings
- Install vertical and lower feeders

Main Generator and Turbine Rotors

- One of three turbine rotors safely delivered to the station and installed
- Two other turbines recovered, delivered and installed
- Alignment of turbines in-progress



- Main generator rotor rewind and reinstalled
- Main generator stator rewind and reinstalled

Emergent Work

- Replace emergency water line
 - ~1000 m buried pipe
- Condenser tube degradation
 - temporary fix - epoxy sealed inserts
 - full replacement in 2012
- Raw service water pipe in concrete degraded

Partnership – Key Stakeholders

- NB Power continues to implement communication plan activities
- Strong sense of partnership with our communities, main contractors and trade unions
- Periodic refurbishment updates to the Canadian Nuclear Safety Commission (Regulator)



Summary

- Safety and quality continue to be our top priorities
- CANDU 6 is a robust design
- Condition Assessment process was effective
- Comprehensive Age management programs are necessary
- Lessons learned will prove valuable to others considering similar CANDU refurbishments
- Daily progress continues

The Point Lepreau GS will restart successfully and will operate safely and reliably for the next 25 to 30 years.

Powering the Future....

