Our Basic Recognition of Fukushima Accident

2 years and 2 months have passed since our Fukushima Accident

➢ The cause of the accident should not be treated merely as a natural disaster due to an enormous tsunami being something difficult to anticipate.

➢ We believe it is necessary to seriously acknowledge the result that TEPCO failed to avoid an accident which might have been avoided if ample preparations had been made in advance with thorough use of human intellect.

Agenda

- 1. Lessons Learned from Tsunami Estimation Process
 - Could we predict an enormous Tsunami and take whatever countermeasures?
- 2. Lessons Learned from Plant Recovery Process - Could we respond to the accident better?
- 3. Challenge for Nuclear Safety Reform

4. Summary

- For the worldwide operators to avoid such an accident



1. Lessons Learned from Tsunami Estimation Process

Facts:


- Underestimated tsunami height for design base.
- Site level was not high enough to prevent inundation of tsunami.
- Equipments as barriers of DiD layer were disabled by tsunami. (common cause failure mode)






Physical protection against Tsunami @KK

The Physical barriers against tsunami are being constructed and the measures which protect power sources and other important apparatus is being taken at Kashiwazaki Kariwa NPS




Reinforcement for Cooling Function @KK



Could we predict an enormous Tsunami and take whatever countermeasures?




Historical Tsunami before March 11th, 2011





Factor1 : Location of the Tsunami Source




| Touch in the materials by Shuto et al., 200 | 07 |
|---|----|
|---|----|

| 1611 | Keityo Sanriku | Mw8.6 |
|------|----------------|-------|
| 1677 | Enpou Bousou | Mw8.2 |
| 1896 | Meiji Sanriku | Mw8.3 |
| 1933 | Shouwa Sanriku | Mw7.9 |

Historical tsunamis, especially over M8 earthquakes, mainly occurred in northern area of northern latitude of 38 degrees.

➢ There was no record about large earthquake along Japan Trench off the coast of the Fukushima Pref.

Factor2 : Effect by Topographic Amplification



Human beings tend to be governed by their own experiences.


compared to na-coast.

145°0'0''E


140°0'0''E




Tsunami height is amplified due to specific topography such as in V-shaped bay. (In this case $b_1 > b_2$)



KYO ELECTRIC POWER COMPANY





Plane view

Fig. Schematic view of tsunami amplification

"Tsunami Assessment Method for Nuclear Power Plants in Japan (2002)" by JSCE (Japan Society of Civil Engineers)


| 成プレ発電器の決決業基本部 | No | Mw | Earthquake | 44* |
|-------------------------|----|-----|---------------------|-----|
| 原子力発電所の津波評価技術 | 1 | 8.2 | 1952 Nemuro-oki | |
| | 2 | 8.4 | 1968 Tokachi-oki | 42* |
| \sim | 3 | 8.3 | 1896 Meiji-Sanriku | |
| | 4 | 8.6 | 1611 Keicho-Sanriku | 40' |
| | 5 | 8.2 | 1793 Miyagi-oki | 3→4 |
| 平成14年2月 | 6 | 7.7 | 1978 Miyagi-oki | 38' |
| 県子力土木奈貝 会 筆波評価部会 | 7 | 7.9 | 1938 Fukushima-oki | 5 |
| | 8 | 8.1 | 1677 Enpo-Bousou | 36* |

>Uncertainties, such as inexperienced event, are taken into account by **parametric study** of the standard fault model.

Earthquakes are assumed in 8 areas individually for numerical simulation based on the historical tsunamis.


Earthquake on March 11th occurred cross over several areas, that was not predicted by any experts.

JSCE 2002 did not consider the tsunami source in the area along the trench of off the coast of Fukushima prefecture.



8

Parametric Study



| Fukushima | Daiichi NPS |
|-----------|-------------|
| Fukushima | Daini NPS |

| 3 | Mw 8.3 |
|---|--------|
| 4 | Mw 8.6 |
| 5 | Mw 8.2 |
| 7 | Mw 8.0 |
| 8 | Mw 8.2 |

General parametric study - location

- strike

Detailed parametric study

- location - strike

- depth dip angle
- slip angle

➤TEPCO carried out general parametric study for area 3, 4, 5, 7 and 8.

➤Tsunami from Area 7 was dominant, and detailed parametric study was conducted for this area.

➢ This parametric study did not cover the uncertainty on whether Tsunami source exists or not.

Did Tepco's Countermeasures for Tsunami Lag Behind Other Electric Power Utilities?

| | TEF | PCO | JAPC | Tohoku EPCO | |
|-----------------------------------|-------------------|-----------------|-------------|-----------------------------|--|
| Event | Fukuehima Daiichi | Fukushima Daini | Tokai Daini | Gnagawa | |
| Ground Level of main buildings | O.P.+10 or 13m | O.P.+12m | H.P.+8.9m | O.P.+14.8m | |
| | | Unit 1in 1972 | | Opit 1 in 1970 O P +2~3m | |

TEPCO was relatively comfortable with the commonly used methodology among all the utilities.

Scer

JSCE

Esta

| disas ter prevention was published by Ibaraki prefectural government | Countermeasure was | Countermeasure was unnecessary. | of the wall around seawater pumps was completed. | unexplained |
|---|---|---|---|-------------|
| Scenario Tsunami for disaster prevention was published by Fukushima prefectural government | Approx. O.P.+5m Countermeasure was | Approx. O.P.+5m Countermeasure was unnecessary. | unexplained | unexplained |
| Latest bathymetric and tidal data in 2009 | O.P.+.6.1m Countermeasure such as raise of the seawater pumps was completed. | O.P.+.5.0m Countermeasure was unnecessary. | unexplained | unexplained |
| Tsunami in 2011 | 0.P.+13.1m (Tsunami height) 0.P.+15.5m Inundation beight) | O.P.+9.1m (Tsunami height) O.P.+14.5m (nundation height) | T.P.+5.4m | O.P.+13.8m |



YO ELECTRIC POWER COMPANY

All Rights Reserved ©2012The Tokyo Electric Power Company, Inc.

y)

ion)

as

Trial Calculation 1 in the Light of HERP in 2008




Fig. Earthquake region by the Headquarters for Earthquake Research Promotion (HERP)

Touch in the materials by HERP, 2002


The Headquarters for Earthquake Research Promotion (HERP) proposed in 2002 that there is a possibility that M8.2 earthquake occur anywhere along the Japan Trench.

- Prior to antiseismic back-check in the light of the seismic guideline, TEPCO carried out a trial calculation in deterministic way.
- HERP showed only the size of fault as 200km×50km and its magnitude as 8.2.
- HERP did not carry out tsunami simulation, and also did not show the parameters which was necessary for tsunami calculation.
- As tsunami source model had not been determined, TEPCO hypothetically applied the model of Meiji Sanriku Earthquake Tsunami in 1896.
- Its magnitude is Mw 8.3, which is larger than the magnitude 8.2 shown by HERP.

| | | 1F | | | | | | | |
|-------------------|-----|-----|-----|-----|----------------------|------|----------------------------|----------------------------|--|
| unit | 1 | 2 | 3 | 4 | 5 | 6 | Northern part (O.P.13m) | Southern part (O.P.10m) | |
| Tsunami Hight [m] | 8.7 | 9.3 | 8.4 | 8.4 | 10.2 | 10.2 | 13.7 | 15.7 | |
| | | | | | | | | | |
| | | 2F | | | | | | | |
| unit | 1 | 2 | 3 | 4 | (O.P.12m) | | Run-up | | |
| Tsunami Hight [m] | 7.6 | 7.2 | 7.8 | 8.2 | 15.5 (Southern part) | | rioigin | | |

TOKYO ELECTRIC POWER COMPANY

Trial calculation 2 of Jogan Tsunami



| | 2F | | | | |
|--------------------|-----|-----|-----|-----|---------------|
| Unit | 1 | 2 | 3 | 4 | (O.P.12m) |
| Tsunami height [m] | 8.0 | 7.8 | 7.8 | 7.9 | No inundation |

Background of Missed Opportunity

TEPCO did NOT:

✓ put more importance on 'consequence' rather than 'probability'

✓ actively promote cross-functional discussions among associated organizations

✓ improve the process to learn the lessons from operational experiences in the world, such as flooding event at Blayais NPS, France

✓ thus take a proactive manner for safety enhancement, even temporarily

That was because:

✓TEPCO believed that severe accident was unlikely then it was not necessary to improve safety measures more, at least immediately (putting off the decision)



2. Lessons Learned from Plant Recovery Process

Facts:

- TEPCO was not sufficiently prepared in responding to such an accident.
- At the Fukushima Daiichi site the <u>command and control structure was</u> <u>degraded</u> in the response to the multi units and also because of external intervention.
- TEPCO management showed distinguished leadership to respond to those unexpected situations, though desirable results did not come out.
- TEPCO <u>employees devoted themselves</u> to save the plants with <u>strong self-accountability</u>, <u>spirit of self-sacrifice</u> and <u>braveness</u>.



o electric power compan'



Could we respond to the accident better?



Accident Response at 1F <Challenging Condition in Main Control Room>



Checked instrumentation in nearcomplete darkness.

Supervised operation wearing full-face mask.

Brought in heavy batteries to restore instrumentations.



Lack of:

instrumentation, communication means, lighting, food, water, sleep, ... ► Increase in: radiation level, fatigue, fear, despair, ...





Accident Response at 1F <Challenging Condition in Field>



Tsunamidrifted obstacles blocked roads.

Hazardous road conditions.






Fire hoses laid for reactor water injection restricted field access by vehicles.


Challenging conditions exacerbated by continual aftershocks/tsunami alerts.



Number of Aftershocks Greater than M 5.0



Overview of the 10-Unit Simultaneous Accidents



Voices from the Field

"In an attempt to check the status of Unit 4 D/G, I was trapped inside the security gate compartment. Soon the tsunami came and I was minutes away from being drowned, when my colleague smash opened the window and saved my life."



> "In total darknoss, I could bear the upportably cound of

SR to o met to o

- "I asked for volunteers to manually open the vent valves. Young operators raised their hands as well."
- "Unit 3 could explode anytime soon, but it was my turn to go to the main control room. I called my dad and asked him to take good care of my wife and kids should I




Unit 1 Main Control Room


D/G: Diesel Generator SRV: Safety Relief Valve S/C: Suppression Chamber

Tokyo Electric Power Company

1F Unit 1 Schematic System Diagram (After Tsunami)



1F Unit 3 Schematic System Diagram (After Tsunami)




Reinforcement for Cooling Function @KK




ikyo electric power company

Accident Response at 2F <Temporary Power Supply and Motor Replacement>



Tokyo electric po



Key Success Factors (1/2)

Availability of <u>plant parameters</u> with <u>DC power supply</u> and <u>back-up cooling function</u> (MUWC) with <u>off-site power supply</u> made 2F recovery process different from 1F.

Leadership was shown to establish a wellprioritized strategy by station management

✓ A well-prioritized restoration strategy to repair and replacement for restoration was established after field walk down in the ERC as follows:

To recover RHR (B) cooling systems by replacing motors and supplying power from survived electrical buses and mobile power vehicles through temporary cable

✓ The strategy on recovery operation was also well established in the MCR, that was Ex. the focus on the uninterrupted water injection by RCIC & MUWC based on the symptom basis EOP.

✓ This clear strategy was communicated to and shared among operators, ERC personnel, all other TEPCO employees, and affiliated companies.

✓ The organization and the personnel could move straight forward to the oal of this strategy well.

Key Success Factors (2/2)

- Prompt restoration with emergency procurement of materials and equipment
 - Coordinated activities of ERC and the headquarters were important.
- Logistics and emotional cares for continuous response activities (mid- to long-term)
 - Emergency response personnel continued to work in a tense atmosphere for a long period while some of their family members were suffered in disaster.
 - ✓ Some responders were diagnosed as **Post-Traumatic Stress Disorder**.
 - ✓ Periodical examination was conducted to minimize stress-related illness.

Organizational integrity during crisis

- ✓ <u>Command and control</u> structure to deal with simultaneous damage of multiple units was maintained.
- ✓ ERC leaders had to manage conflicts, fears and worries in response staff including those temporarily dispatched to the site.
- Good teamwork had been already developed prior to the accident.

kyo electric power company

3. Challenge for Nuclear Safety Reform



How successful and effective (or not) the challenges for organizational and cultural changes and to enhance nuclear safety were before the Accident?

Exs.

✓ Nuclear Renaissance Activities

 ✓ Lessons Learned from Niigata Cyuetsuoki Earthquake @KK site



Initial Recognition on 2002 Scandal & Countermeasures taken

TEPCO has been making changes required in:

- 1. Organizational Culture
 - Safety first not yet permeated
 - Vertical silo based on complacency
 - Lack of learning/questioning attitude
 - Need to improve business ethics
- 2. Work Process
 - Safety culture not built into the processes
 - Unclear accountability and authority in the work processes
 - Ambiguous roles between TEPCO and manufacturer/subsidiaries, as well as between the Headquarters and sites
- 3. Quality Assurance
 - Ineffective oversight by experienced and knowledgeable people
- 4. External Interface METI, Local Government, Local Community, etc.

- Insufficient opportunities to have reasonable discussion for pursuit of

Remedial Actions taken:

- 1. Oversight committee, in-house oversight group & corporate ethics committee
- 2. Organizational change: implemented and plans discussed by Managing Board

(ex. Quality & Safety Group at each site, New Maintenance Department – responsible for all of planning, management, supervision and engineering)

- 3. Procedure/manual development meeting new QA structure
- 4. Ethics education and ethics hotline (in house): functional
- 5. CAP (Corrective Action Program): functional and "Passport" has been applied
- 6. Modernization of Maintenance Practices: RCM/CBM implemented on a part of equipments and evaluated (at 1F site)



further improvement for pursuit of excellence

Nuclear Renaissance Activities

Nuclear Renaissance Activities for pursuit of Excellence


Since the TEPCO scandal in 2002

Benchmark Activities (Learning from the Bost Practices) Process Improvement (Core Activities: Implementation)

The reason why this activity was not fully successful was that:

Sponsorship had not been shown continuously by top management

Thorough focus on safety was not clearly demonstrated by top management



Improvement of Crisis Management

Emergency Response Center was unavailable immediately after the quake; plant staffs had to collect information outside of the office building. (@KK site)





Newly built Seismic-Isolated Building


Without this newly built Seismic-Isolated Building (Incl. Emergency Response Center), the post-accident activities could not have been carried out.



Improvement of Crisis Management

Reinforcement of Emergency Preparedness

- TEPCO Team for immediate fire fighting
 - On-site fire brigade on around-the-clock standby
 - Deployment of chemical fire engine and fire pump truck with a water tank



Reflecting Fukushima Accident

During the design stage and afterward, <u>ample</u> <u>consideration</u> was <u>not</u> given to <u>common cause failures</u> originating in <u>external events</u>, which led to a severe situation where almost all the power supplies and safety system functions were lost.

Continuous efforts to reduce risks were not ample, including the collection, analysis and utilization of information on <u>safety enhancement measures</u> and <u>operational experiences in other countries</u> and/or the consideration of <u>new technical knowledge</u>.

Preparation for a severe accident was somewhat deficient in terms of facility and personnel deployment.

Challenge for Nuclear Safety Reform

Objective: Strengthen Safety Culture in TEPCO.

Root cause analyses: Reviewed safety activities in the 2000s and identified deficiency in safety awareness, engineering and communication ability.

Safety Awareness

- Lack of awareness that it was important to improve safety continuously
- Reluctant to improve safety measures beyond regulatory requirements
- Overestimate current safety features reliability

Engineering Ability


- Lack of awareness that external events cause SBO, which is highly likely to lead to severe accidents
- Lack of ability to develop effective safety measures with limited resources in short period.
- Cannot use information effectively from overseas or other power stations.

Communication Ability

 Reluctant to acknowledge required improvements for fear of losing public confidence in nuclear safety

Negative Spiral of Insufficient Accident Preparation

We believed safety had been established and concerned capacity factor mainly then reluctant to improve safety measures.



Action Plan

1.Enhance safety awareness of top management

*IAEA Senior Management Workshop on Safety Culture under consideration

- 2.Establishment of <u>Nuclear Safety Oversight</u> <u>Organization (NSOO)</u>
- 3.Reorganize <u>emergency response team</u> based on Incident Command System (ICS)
- 4.Improve <u>engineering ability</u> to propose Defense in Depth (DiD) safety measures
- 5.Establish <u>risk communicator positions and Social</u> <u>Communication Office</u> to build trust with local community and public

6.Enhance on-site staff technical capabilities

TOKYO ELECTRIC POWER COMPANY

4. Summary

Nuclear operators must recognize that even the most superior engineers <u>cannot be perfect enough to cover all the</u> <u>aspects for safety enhancement</u> in a timely manner.

Nuclear operators should assume that something unexpected could happen in the nuclear business even tomorrow, being <u>much more aware of the risk existing</u> in this business than the people in the other industries, and <u>continuously learn the lessons from any others in a modest</u> <u>manner. Self-complacence could hamper these challenges.</u>

> In order to achieve the above it is definitely <u>necessary</u> for nuclear operators to routinely collaborate with other people, other groups, other companies and other countries <u>as if they</u> were their neighbors.



4. Summary (Continued)

Communication skills and understandings of behavior science and organization dynamics at a certain level are critical for nuclear operators, that could be essential factors for robust safety culture to be developed.

Though unique efforts like blind training to improve the capability to respond to the unexpected might be valuable for nuclear operators in parallel with efforts for making the experience basis more robust, the ultimate measures might be to continuously improve their own fundamental engineering capabilities and firsthand technical skills.

Thanks for your attention !

&

Thank you so much for all of your supports you have already provided us and in anticipation of your continuous supports in future !



Reference




2F Recovery Process



Response at Main Control Room and TSC

• Operator's initial response

- MSIVs closed manually, and reactor pressure controlled by SRVs.
- RCIC actuated manually to maintain reactor water level. RCIC repeated automatic trip due to high water level signal and manual restart.
- MUWC actuated for alternative water injection measure introduced for Accident Management, as stated in EOP manual for seamless water injection.
- Reactor depressurized and RCIC stopped due to steam pressure decrease.
- Water level maintained by MUWC.




Tokyo Electric Power Company

All Rights Reserved ©2012The Tokyo Electric Power Company, Inc.


Successful Reactor Cooling during Transient

Securing uninterrupted water injection throughout the depressurization process with RCIC at high pressure condition and MUWC at low pressure condition was a critical factor for successful reactor cooling.



Efforts to Control Temperature and Pressure in PCV

- S/C water temperature reached 100°C (212F).
 → It eventually increased up to about 130°C (266F).
- Water injected to S/C through Hydrogen Recombiner cooler discharge line in order to mitigate temperature and pressure increases.
- Alternative injection to reactor using MUWC switched to D/W spray, then S/C spray.
- S/C temperature decreased after restoration of RHR.



System Status after the Tsunami at 2F

| System | | Unit 1 | | Unit 2 | | Unit 3 | | Unit 4 | |
|--|----------------|--------|---|--------|--|--------|--|--------|--|
| | RHR(A) | × | inoperable due to the loss of power source and cooling system | Δ | inoperable due to the loss of cooling system | Δ | inoperable due to the loss of cooling system | Δ | inoperable due to the loss of cooling system |
| RHR(A) including cooling systems | RHRC/RCRS(A,C) | × | inoperable due to the submerge of power source and motor | × | inoperable due to the submerge of power source and motor | × | inoperable due to the submerge of power source and motor | × | inoperable due to the submerge of power source and motor |
| | EECW(A) | × | inoperable due to the submerge of power source and motor | × | inoperable due to the submerge of power source and motor | × | inoperable due to the submerge of power source and motor | × | inoperable due to the submerge of power source and motor |
| LPCS | | × | inoperable due to the loss of power source and cooling system | Δ | inoperable due to the loss of cooling system | Δ | inoperable due to the loss of cooling system | Δ | inoperable due to the loss of cooling system |
| EDG(A) | | × | inoperable due to submerge | Δ | inoperable due to the loss of cooling system | Δ | inoperable due to the loss of cooling system | Δ | inoperable due to the loss of cooling system |
| RHR(B) including cooling systems | RHR(B) | Δ | inoperable due to the loss of cooling system | Δ | inoperable due to the loss of cooling system | 0 | stand-by | Δ | inoperable due to the loss of cooling system |
| | RHRC/RCRS(B,D) | × | inoperable due to the submerge of power source and motor | × | inoperable due to the submerge of power source | 0 | stand-by | × | inoperable due to the submerge of power source and motor |
| | EECW(B) | × | inoperable due to the submerge of power source and motor | × | inoperable due to the submerge of power source | 0 | operation | × | inoperable due to the submerge of power source |
| RHR(C) | | Δ | inoperable due to the loss of cooling system | Δ | inoperable due to the loss of cooling system | 0 | stand-by | Δ | inoperable due to the loss of cooling system |
| EDG(B) | | × | inoperable due to submerge | Δ | inoperable due to the loss of cooling system | 0 | operation | Δ | inoperable due to the loss of cooling system |
| RWCU | | Δ | inoperable due to the loss of cooling system | Δ | inoperable due to the loss of cooling system | Δ | inoperable due to the loss of cooling system | Δ | inoperable due to the loss of cooling system |
| MUWC (alternative water injection) | MUWC(B) | 0 | stand-by | 0 | stand-by | 0 | stand-by | 0 | stand-by |
| RCIC | | 0 | stand-by | 0 | stand-by | 0 | stand-by | 0 | stand-by |

× ; bss of function (power, pump or motor noperable).2The Tokyo Electric Power Company, Inc.

Field Walkdown


In order to establish a well-prioritized restoration strategy, degree of damage and possibility of short-term restoration must be understood through walkdown.

Challenges in conducting field walkdown

- Under continuous tsunami alerts, walkdown must be done in the field where a lot of debris, openings and flooding areas existed in the dark.
- Preparation for emergency evacuation in case of further tsunami and other safety measures for personnel going out to the field.
- Successful access to the field was 6 hours after the tsunami flooding.

• Field walkdown after the tsunami

- Plant equipment status checked / component functionality verified.
- Results were summarized and shared at TSC.
- TSC set priorities on recovery of RHR (B) cooling systems by replacing motors and supplying power from survived electrical buses and mobile power vehicles through temporary cable.



Logistics in Emergency Situation

Procurement and transportation of Materials and Equipment

- Emergency procurement of motors, cable, mobile power vehicles, fuel oil and mobile transformers with close cooperation between site TSC and corporate ERC.
- Rated output of some motors were not the same as that of the original motors.
- \rightarrow TSC determined to install them based on the evaluation of actual load conditions.

• Difficulties experienced in logistics

- Motors were transported from Toshiba by a chopper of SDF and from Kashiwazaki Kariwa NPP by trucks.
- Securing redundant communication measures were critically important when major highway was damaged and public cell phone services were disrupted.

Mobile Power Vehicles



Necessary materials and equipment prioritized and listed

| 61 | ファイル(F) 編集(E) 表示(V) 挿入(D) 書式 | (O) ツール(T) データ(D) | ウインドウ(| W0 AU-7040 | | | |
|----------|---|------------------------|---------|-----------------|-----------|----------|-----|
| | 😂 🖬 🖪 🖨 🖪 💁 🖏 🕷 🕷 🖬 | 9 | A | | 1100% - @ | E MS D12 | A |
| - | | 🗗 🗸 🐴 l =) + (= + l 🖁 | 5 Z * Z | + A+ 🛄 🗠 | | E | ~~~ |
| | G10 • A | - | | | | - | |
| | A | В | C | (|) | E | |
| 1 | 工事概要 屋内外の仮設ケーブル付設・接続 | | | | | | |
| 2 | 産内外の服設リーフル内設・接続 | | | | | | |
| 4 | ・P/C1A-1~ T/B大物機入口~ | 屋内の豊心の海道また | 2 fra E | | \ | | |
| # 5 | P/CIA-I/~ I/BAMBAU/~ | 150sg CVT(2条) | | (うち屋内 | | | |
| 6 | | 10080 011(25%) | 20011 | (J) En | 11710/ | | |
| 7 | ・P/C4D-1~T/B大物粉入設置の | の仮設Trまで for F | ECW(3 | 居穂) | | | |
| â | 17 040 1 17 07(10)82/02082 | 150sg CVT(2条) | | -5 w/o (うち屋内 | 100m) | | |
| 9 | | | | 10-10-12 | | | |
| | ※屋外作業はタイペック着用要 | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |
| 13 | 不足資材 | | | | | | |
| 14 | ユニック | 1台 | ← | 3号T/Bエリ: | アになし構内で | 。確保可能 | n? |
| 15 | ケーブルジャッキ | 1組(ローラー) | | | | | |
| | 沿線コロ | | | | | | |
| | ケーブルカッター(バッテリーor人力) | 1台 | | | | | |
| | 圧着用工具(バッテリーor人力) | | | | | | |
| | ケーブル直ジョイント用スリーブ(150sg) | 207 | | | | | |
| | 圧着端子(150-16) | 207 | | | | | |
| | 圧着靖子(150-12) | 207 | | | | | |
| 22 | | | | | | | |
| | エンパイヤクロス | | | | | | |
| | エフコテーブ | 20巻 | | | | | |
| | 絶録テーブ | 20巻 | | | | | |
| 26 | | | | | | | |
| | 必要人員 | 電気工事士等専門職 | | | | | |
| 28 29 | | 30名程度 | | | | | |
| 29 30 | | | | | | | |
| 30 31 | 管理区域変更(B→A) | 1号機T/B 1F | | | | | |
| 32 | 自社区成点天(D-'A) | 151001/D1F 4号操T/B1F | | | | | |



Fuel oil delivery to the site

| 図形の調整(2)・ トーオードショイブロット 🔪 🗖 〇 🔤 🗃 🖓 🖉 🔯 🔕 ・ 🖉 ・ A ・ 〓 亜 寺 🗃 🍙


Emergency Restoration Efforts in the Field

- Pumps of RHR cooling systems (RHRC, RHRS, EECW) were inspected.
- Motors were replaced for pumps in RHRC and EECW.
- In order to restore the inundated electrical buses, temporary cable and high voltage mobile power vehicles were deployed.
- Temporary cable was laid from survived power cubicles in Rad-Waste Building and Unit 3 House Duilding Drawing made at TSC for temporary cable laying

Motor replacement



)KYO ELECTRIC POWER COMPAN



System Status after Emergency Restoration at 2F

| Syster | n | Unit 1 | | Unit 2 | | Unit 3 | | Unit 4 | |
|--|----------------|--------|---|--------|--|--------|--|--------|--|
| | RHR(A) | × | inoperable due to loss of power source and cooling system | Δ | inoperable due to loss of cooling system | Δ | inoperable due to loss of cooling system | Δ | inoperable due to loss of cooling system |
| RHR(A) including cooling systems | RHRC/RCRS(A,C) | × | inoperable due to submerge of power source and motor | × | inoperable due to submerge of power source and motor | × | inoperable due to submerge of power source and motor | × | inoperable due to submerge of power source and motor |
| | EECW(A) | × | inoperable due to submerge of power source and motor | × | inoperable due to submerge of power source and motor | × | inoperable due to submerge of power source and motor | × | inoperable due to submerge of power source and motor |
| LPCS | | × | inoperable due to loss of power source and cooling system | Δ | inoperable due to loss of cooling system | Δ | inoperable due to loss of cooling system | Δ | inoperable due to loss of cooling system |
| EDG(A) | | × | inoperable due to submerge | Δ | inoperable due to loss of cooling system | Δ | inoperable due to loss of cooling system | Δ | inoperable due to loss of cooling system |
| | RHR(B) | 0 | operation | 0 | operation | 0 | operation | 0 | operation |
| RHR(B) including cooling systems | RHRC/RCRS(B,D) | 0 | operation | 0 | operation | 0 | operation | 0 | operation |
| | EECW(B) | 0 | operation | 0 | operation | 0 | operation | 0 | operation |
| RHR(C) | | 0 | stand-by | 0 | stand-by | 0 | stand-by | 0 | stand-by |
| EDG(B) | | Δ | operable using tie-line from unit #2 | 0 | stand-by | 0 | stand-by | 0 | stand-by |
| RWCU | | Δ | inoperable due to the loss of purge line | Δ | inoperable due to the loss of purge line | Δ | inoperable due to the loss of purge line | Δ | inoperable due to the loss of purge line |
| MUWC (alternative water injection) | MUWC(B) | 0 | stand-by | 0 | stand-by | 0 | stand-by | 0 | operation |
| RCIC | | × | inoperable for loss of core pressure | × | inoperable for loss of core pressure | × | inoperable for loss of core pressure | × | inoperable for loss of core pressure |

× ; bss of function (power, pump or motor noperable). 2The Tokyo Electric Power Company, Inc.

Organization and Management Features

Accident mitigation by applying EOP and AMG

Prioritized restoration strategy based on Field Walkdown

- Prompt restoration with success of emergency procurement for materials and equipment
- Logistics for long term emergency response

Organizational integrity: Leadership, Communication, Accountability, Professionalism

Design/Engineering Features

Availability of most of M/C, P/C and Battery
 Availability of off-site power

Details on Action Plan

Countermeasures 1~6



[Main Points]

- *The management must be strongly conscious of the special risks inherent in nuclear power, be aware that nuclear power operators bear responsibility for safety, and demonstrate leadership in order to raise safety awareness throughout the organization.
- *Nuclear leaders (executive officers, site superintendents, corporate general managers) must personify appropriate behavior, be evaluated, and work to improve their OWN abilities.
- *Management needs to take the initiative to imbue a safety culture throughout the organization.

[Countermeasures]

- *Increase knowledge about the safety required for nuclear power, and implement OUr own nuclear safety reforms to disseminate a safety culture throughout the organization.
- * Conduct quarterly 360-degree evaluation (comprising evaluations from superiors, peers, subordinates, as well as the opinions of contractors and people in siting communities) of nuclear power leaders and provide feedback to the leaders evaluated.

[Management (all executive officers)]

- * Study examples of management reform successes and failures at other companies
- $\boldsymbol{*}$ Basic principles of nuclear safety design and safety culture
- * Causes of Fukushima nuclear accident and countermeasures
- * Other topics

[Nuclear Leaders (executive officers, site superintendents,

- corporate general managers)]
- In addition to the items listed on the left,
- * Refresh plant operational knowledge through upper level courses at operation training center, etc.
- * Acquire the latest knowledge, conduct plant walkdowns, etc.


Countermeasure 2: Enhancement of Oversight and Support for Management

[Main Points]

* The Board of Directors of a nuclear operator is obliged to oversee nuclear safety. For that purpose, the required support organizations will be established, which will report the necessary information to the Board of Directors.

[Countermeasures]

- * Establish a "Nuclear Safety Oversight Office" to assist the TEPCO directors in decision making.
- * The Nuclear Safety Oversight Office will invite its personnel in charge from outside the company to evaluate activities related to nuclear safety from a position independent of those implementing such activities, and to both monitor and advise those doing the implementation while also reporting to the TEPCO Board of Directors.
- * Additionally, efforts will be made to enhance the roles of middle management and Chief Reactor Engineer.



Countermeasure 3: Reform of Emergency Response Organizations at the Power Stations and Headquarter


[Main Points]

* After the disaster, the activities at the site was in disarray because "the chain of command system was unclear" and "information was not fully shared" as well as other factors.

[Countermeasures]

In emulation of the Incident Command System (ICS) as characterized below that serves as a standardized emergency response structure in the U.S., reorganize the emergency response organizations at TEPCO power stations and the Headquarter.

- Limit the number of people a single manager oversees to 7 at most
- Clarify division of responsibilities chain of command system (follow only the instructions of direct superiors)
- Clarify the division of roles (decision-making authority should be given to the commander in the field)
- Flexible organizational structure that can expand or contract depending on the scale of a disaster
- Prepare and put into use modalities and tools for sharing information efficiently throughout the organization
- Clarify skills and requisites, and provide thorough and going education and training



Countermeasure 4: Enhancement of Risk Communication Activities (1) Establishment of Risk Communicator Positions

[Main Points]

*We need to <u>extricate ourselves from "thought-stopping patterns" which are based on the assumption</u> that, if risks are announced, requests for excessive countermeasures will be demanded by regulators and siting communities, necessitating a reactor shutdown.

*TEPCO, as a company that caused a severe accident, has <u>the duty to make risks known and convey</u> <u>countermeasures broadly to the general public</u>.

Given the above challenges, we will **establish the specialist position of "risk communicator"** for handling risk-related communications from a position Close to management and nuclear power leaders.

[Countermeasures]

- * Risk communicators will make <u>proposals</u> to management and nuclear power leaders, from society's perspective, <u>regarding strategies for explaining</u> risk awareness, formulation of countermeasures in keeping with public announcements, and the limits thereof. They will also <u>undertake risk communications</u> <u>based on the policies developed</u>.
- * Risk Communicators will regularly engage in dialogue with others and solicit advice and suggestions from outside experts while <u>developing skills</u> for carrying out fruitful dialogues with site communities as well as the public more generally.



Countermeasure 4: Enhancement of Risk Communication Activities (2) Establishment of Social Communication Office

[Main points]

We did not have an accurate understanding of the present situation around us, and our sensitivity to the feelings of people in siting communities and the general public was obtuse, which inflamed public anxiety (response to loss of power supply accident at Fukushima Daiichi Nuclear Power Station, etc.).


Also, we received severe comments from the Third-Party Investigation Committee on TEPCO's Response to the National Diet of Japan Nuclear Accident Independent Investigation Commission (NAIIC), which indicated that our company has communication problems.

Based on such facts, we must urgently make improvements by delving into corporate culture problems with the Nuclear Power Division playing a central role in order to appropriately communicate with society.

Reflecting on the fact that previous improvement activities could not delve into deep-rooted corporate culture problems, we will invite people outside the company, thereby bridging the gap between our way of thinking and judgment and the standards accepted by society at large, and, at the same time, we will put a framework in place to prevent aggravation of risk.

[Countermeasures]

•Invite a person from outside the company to become the "SC General Manager", establish the organization (SC Office) which is directly responsible to the President, and implement the following;



<Ref.> Regarding Comments *1 by the Third-Party Investigation Committee on TEPCO's Response to NAIIC

- * As for misleading explanations given to the National Diet Nuclear Accident Independent Investigation Commission (NAIIC), TEPCO received the following three improvement requests from the Third-Party Investigation Committee:
 - Enhance employee education in regard to negotiations with external organizations
 - Organize a cooperative framework and a support framework among employees
 - In regard to the need for showing the attitude of TEPCO as a whole to the external organizations, build an organizational structure in which the directives from the top management spread down among all employees, and the employees are able to consult top management at an early stage.

We think implementation of Countermeasure "Establishment of Social Communication Office," in addition to the aforementioned Countermeasure 1 "Reform Starting from Management" and Countermeasure 4 (1) "Establishment of Risk Communicator Positions," will prompt a revamping of the organization through educational activities for the company, which will result in solution to the request by the Third-Party Investigation Committee.

*1: Third Party Investigation Committee on TEPCO's Response to NAIIC's "Report of Verified Results (March 13, 2013)"



<Ref.> Roles of the SC Office and Nuclear Power Risk Communicators

* <u>The SC Office will utilize nuclear power risk communicators ("RC") as the pivotal points for risk</u> management in responding to external organizations on behalf of the entire Nuclear Power <u>Division.</u>

Input from RCs to SC Office

- Demonstrate the faculty to pick up information about nuclear power risks
 - Make proposals about risks to be administered by management in regard to risks considered to have a significant influence on management as based on information provided by the Nuclear Power Division and in responding to external organizations on a daily basis.
 - RC will engage in the management of cases on a daily basis (time limit control) about the risks faced by the Nuclear Power Division and the matters of concern when responding to external organizations, thereby sharing information on a timely basis.

Output by RCs (Implementation of risk communication)

- * Implement external communication activities concerning nuclear power risks
 - In response to SC Office's proposal of the policy to publically announce important cases, RCs will create talking points and implement risk communication personally at each site.
 - RCs will acquire the perspective of society through daily communication about nuclear power, and, at the same time, will play some role in educational activities for the Nuclear Power Division.

Countermeasure 5: Enhancement of Ability to Propose Defense in Depth Safety Measures

[Main Points]

In order to decrease residual risks to a socially permissible level, it is necessary to <u>continuously make an</u> <u>effort to enhance safety improvement measures</u>. For this reason, we will construct a system for developing the technological capability for <u>promptly proposing</u> the enhancement of <u>highly cost-effective</u> <u>measures to improve safety</u> in accordance with defense in depth. Also, we will organize our working environment in keeping with enhanced technological capability.

[Countermeasures]


- * From a standpoint of accumulating defense in depth, we will reassess operational processes.
- Promote cross-organizational proposals so that planning and implementation of safety measures will take root as routine work, and we will accumulate a series of successes which realize outstanding proposals for improvement (<u>safety improvement competition</u>)
- From a standpoint of building a defense-in-depth structure, <u>draw lessons from operational experiences</u> information from both Japan and other countries
- Conduct hazard analyses of external events causing rare though severe situations
- Frequently conduct reviews of activities related to nuclear safety (safety review activities)
- * We will <u>improve our working environment</u> in order to effectively promote improvement of the processes described above.
 - -Improve performance evaluation related to nuclear safety
 - -Reassess operations focused heavily on evidence
 - -Improve cross-organizational capability for solving problems
 - -Reassess personnel exchanges between divisions

Countermeasure 6: Reassessment of Non-Emergency Power Station Organization and Enhancement of On-Site Staff Technical Capability for Direct Maintenance Work

[Main Points]

Reassess power plant organization under normal conditions with the goal of <u>bolstering capability to take a comprehensive view of nuclear safety</u>. Also, strengthen operator's ability and reform the organization to enable maintenance work to be directly performed by maintenance sections so that <u>TEPCO employees can carry out the first response after an accident</u>, and also foster the applied skills for dealing with upanticipated situations.

[Countermeasures]



- * Bolster Abilities to perform direct works
 - Operators: Train in how to connect power-supply vehicles that the recovery units undertake and conduct regular maintenance work and equipment diagnostics (data collection, simple diagnoses, etc.)
 - -Maintenance personnel: Develop applied skills by direct maintenance work so as to be able to, when necessary, inject water into a reactor and install or replace temporary equipment.