


# Degradation Monitoring of G.A. Siwabessy Research Reactor's Secondary Cooling Pipe



Roziq Himawan

Indonesian National Nuclear Energy Agency (BATAN)

International Conference on Research Reactor: Safe Management and  
Effective Utilization, 14-18 November 2011, Rabat, Morocco


# Introduction of G.A. Siwabessy Research Reactor

- One of three research reactor operated by BATAN
- Open pool type reactor
- 30 MW thermal power
- Multi purpose research reactor
  - Isotope Production
  - Material testing
  - Other Irradiation facility
- First criticality was reached in 1987



# Introduction of G.A. Siwabessy Research Reactor

- Flux neutron  $10^{14}$  n/cm<sup>2</sup>
- Fuel Element  $U_3Si_2Al$
- Number of fuel elements : 40
- Number of control rod : 8
- Moderator : water
- Coolant : water



# Ageing Management Programme for G.A Siwabessy Research Reactor

- Ageing Management wasn't considered in the initial operation
- After 16 years operation, many degradation phenomenons of SSC were observed, especially on secondary cooling system
- In 2003 AMP for research reactor was established (IAEA – EBP : NTC, Workshop, Experts mission)
- In-service inspections have been conducted to RR's SSC (mechanical components, electrical components, etc.)
- Many NDT methods have been applied to conduct ISI




## Objectives of ISI

- To understand the degradation level of the secondary cooling system
- Mitigation/improvement/modification to minimize the degradation effects



# Secondary Cooling System



## Secondary Cooling System

Secondary Cooling system consists of many components, including

- Cooling tower
- Pumps
- Valves
- Piping system
- Mechanical Filter



## Secondary Cooling System

### Specifications of pipe in secondary cooling system

	Pipe #1	Pipe #2	Pipe #3
Material	R St. 37 .2	R St. 37 .2	Carbon steel
Standard	DIN 1626 Bl. 3	DIN 2673	ASTM A53-B
Diameter (mm)	813	610	510
Thickness (mm)	8	6,3	9





## Secondary Cooling System

ISI methods applied to secondary cooling system

- Visual Inspection → Surface inspection
- Ultrasonic Flaw Detector → welded parts
- Ultrasonic thickness gauge → thickness measurement
- Ultrasonic thickness mapping → fine thickness mapping



# Ultrasonic Flaw Detector



International Conference on Research Reactor: Safe Management and Effective Utilization,  
14-18 November 2011, Rabat, Morocco

# Ultrasonic Thickness Gauge



# Ultrasonic Thickness Mapping

## Ultrascan 5

Allow scanning up to 1mm in pitch.



# Inspection History

- First inspection was performed in 2004
  - visual inspection
  - flaw detection
  - thickness measurement
- Second inspection was performed in 2007
  - thickness mapping
- Second inspection was performed in 2009
  - thickness measurement



# Inspection Methods

## Visual Inspection


- Internal surface → using CCD Camera
- External surface → human eyes

Flaw Detection : According to ASME Section V






# Ultrasonic Thickness Measurement




# Ultrasonic Thickness Measurement (2004)





# Ultrasonic Thickness Measurement (2009)





# Inspection Results

## Visual Inspection



# Inspection Results






## Inspection Results

Flaw detection : No significant indication observed

Thickness mapping : Indicated Pitting corrosion





# Inspection Results





# Inspection Results





## Consideration

Measurement results which larger than initial thickness are caused by

- Paint layer
- Corrosion (product)
- Sedimentation from cooling water (impurity of raw water, chemical agent)




# Inspection Results





# Inspection Results



## Conclusion

- Degradation of pipe are due to homogenous and pitting corrosion rather than erosion-corrosion (flow accelerated corrosion)
- Improvement of water treatment are needed to suppress corrosion occurred in the internal surface



## Next plan activity

- Core structure assessment
- Pool liner inspection
- Surveillance programme





Thank you for your attention